Qty:

: HINGE BRACKET

: D28581

: 6/15/2006

: N/A

: D2858 REV B

User:

Monday, 5/15/2006 11:16:27 AM

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 27127

Estimate Number

:10348

P.O. Number

Previous Run

: N/A

: 5/15/2006 This Issue

Prsht Rev. First Issue

: NC

: 5/15/2006 : 26035

S.O. No. : N/A

Type

: MACHINED PARTS

Checked & Approved By

Comment

Written By

: Est C

Removed P/O for powder coat EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M6061T6B1500X01250

6061-T6 Bar 1.5" x 1.25"

4.2412 f(s)

Comment: Qty.: Total: 0.1767 f(s)/Unit

Material: 1.50" X 1.25"

6061-T6 (QQ-A-225/8 or QQ-A-250/11 or QQ-A-200/8)

(M6061T6B15001250) Batch <u>M10038U</u>

BAND SAW

Each

24 Um:

2.0

BAND SAW

Comment: BAND SAW

Cut blanks 6.02"

Note: 1 Blank Makes 3 Parts

x 24

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #



Comment: HAAS CNC VERTICAL MACHINING #1

- 1-Machine per folio D2858-

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Page 1

Form: rprocess

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCE	DURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector		
~										
		•								
	·									
NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		December of NO	Corrective Action Se	ection B	\	4.				

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B	Verification	A				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector		
	·									
		•								
					1					

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date: 06/05/29
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Monday, 5/15/2006 11:16:27 AM Kim Johnston User: **Process Sheet** Drawing Name: HINGE BRACKET Customer: CU-DAR001 Dart Helicopters Services Part Number: D28581 Job Number: 27127 Job Number: Seq. #: **Machine Or Operation:** Description: SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Tumble 2-Deburr any rough edges after tumbling HAND FINISHING1 HAND FINISHING RESOURCE #1 6.0 Comment: HAND FINISHING RESOURCE #1 Acid etch and Alodine as per QSI 005 4.3 INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 8.0 POWDER COATING Comment: POWDER COATING Powder Coat Gloss White (Ref. 4.3.5.1) per Dart QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: INSPECT POWDER COAT PACKAGING RESOURCE #1 10.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock 06/05/20 Location:_S13 11.0 DC DOCUMENT CONTROL 206/05/29 V 06/05, 29 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Form: rprocess

Page 2

Dart Aerospace I td

1.1.1

		W	ORK ORDER CHANGES	3			·	
STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
					"			
		WORK ORD	ER NON-CONFORMAN	CE (NCR	.)			
	Description of NC	escription of NC Corrective Action Section B			Verifi	cation	Annroval	Approval
STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date			Design Mgr	QC Inspector
	. •							
,								
							:	
			•					
	·							
					-			
):	PAR #:	Fault Catego	ry: NCR:	Yes No	DQA:		Date:	
	STEP	STEP Description of NC Section A	STEP Description of NC Section A Initial Design Mgr	WORK ORDER NON-CONFORMAN STEP Description of NC Section A Initial Design Mgr Action Description Design Mgr Design Mgr	WORK ORDER NON-CONFORMANCE (NCR STEP Description of NC Corrective Action Section B Initial Design Mgr Action Description Design Mgr Design Mgr Design Mgr Description Descri	STEP PROCEDURE CHANGE By Date WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Corrective Action Section B Section A Date Initial Design Mgr Dessign Mgr Date Verification Description Desc	STEP PROCEDURE CHANGE By Date Qty WORK ORDER NON-CONFORMANCE (NCR) Corrective Action Section B Corrective Action Description Sign & Date Design Mgr Design Mgr Date Verification Section C	STEP PROCEDURE CHANGE By Date Qty Approval May / Design M

Part No:	PAR #:	_ Fault Category: _	NCR:	Yes No	DQA:	Date:	
NOTE: Date & initial all entries				QA: N/C CI	osed:	Date:	
H:\forms\Quality Assurance\approved forms	s\NCRWO revC						1

Copyright 1998 by DART AEROSPACE L

DART AEROSPACE LTD	Work Order:	27127
Description: Linge bracket	Part Number:	D 2858-1
Inspection Dwg: D2858 Rev: 8		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

. /	•		
X	First Article		Prototype
		L	riototype
			

					-71	
Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension	,	Dimension	,		Inspection	
1.476	± .010	1.477				
Ø.400X-063	(~	-401 X-061				
Ø.171	- 0 + -002	.173		·		
5.125	±.010	1.125				
. 328		-328				
. 820	v	.820				
.875		. 875				
. 342		.342				
1.56	+ .030	1.565				
.354	7.010	.354	/			
Ø./66	+.005	-168				
. 965	±.010 , +.005 001 //	.966	/			
.7/7	+ .010	.719	/	`		
.147	. ~	148				
. 697	•	.698				
. 229	· .	.230				
7.125	~	.125				
(.063		-063				
. 126		- 127	<u> </u>			
.630	.•	.630				
		,	,			
					-	
	·		r.			•

	, ,			
Measured by:	Audited by:	In	Prototype Approval:	
Date: 06/05/24	Date:	06/05/24	Date:	

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/RF	